

# Firmware Release Note



<b>Model : SL-M2021W/XIL</b>	<b>Date :</b>	<b>February 3, 2015</b>
------------------------------	---------------	-------------------------

<b>Version</b>	<b>Category</b>	<b>Change Description</b>
<b>V3.07.01.05</b> (14-Nov, 2014)	Fix Defect	[Google Cloud Print] Fix to the latent issue and enhancement to UI. Google Cloud Print is not perfectly control the "chunked" data. Compatibility of OTG cable. Can not print when PJI DOCNAME has spaces around 50th byte.
<b>V3.07.01.07</b> (16-Jan, 2015)	Add Func.	Google Cloud Print 2.0 feature
	Fix Defect	Paper jam error doesn't be cleared by pressing the Print Screen button

※ Note

- Please do not turn off the printer and your computer until firmware update finishes.
- If you are using USB connection, disconnect all other USB printers from the PC.
- The firmware update you are about to install has been tested for compatibility with Samsung toner cartridge products ONLY.  
Installing The upgrade may cause a non-Samsung toner cartridge to malfunction.
- Do not run your printer during the firmware update.(Do not have any print job)